

Use Soldering iron with earth.  
Solder in cloth-gloves.  
Apply insulation coating at the area shaded  
in the diagram

Soldering Material:  
Solder CCS  
Flux L-35

